

#### CLIENT

# CONFIDENTIAL

### LOCATION:

New York

DESIGN START: 2004

DESIGN COMPLETE: 2004

CONSTRUCTION COMPLETE: 2005



A not-in-use Honeywell temperature controller found that was demolished & removed

Found loose Low Voltage Wirings

Found two missing breaker blanks in the Panel

#### **SCOPE OF WORK**

**Evaluate Existing Systems and Design Upgrade** 

## PROJECT DESCRIPTION

A&J Consulting was retained to evaluate the existing mechanical equipment rooms & associated system and design an upgrade for the same.

Several live electrical wiring was found exposed and dangling in the mechanical equipment rooms. Some equipment and utilities such as steam, condensate, chilled water, sanitary piping and electrical conduits were no longer in use, but remained in place causing confusion, congestion and safety concerns.

A&J conducted the field survey and identified all the abandoned equipment, piping, system components and services, which need to be demolished/removed and re-designed the upgrade.